



To

The Principal
SKS International Gurukul
Near NIT, Kirmach Road
District Kurukshetra

Subject: No. 3644 Dated: 13-10-23
Issue Certificate for School Building Safety.

Reference: Your office letter No.SKSIG/2023/1185 dated 12.10.2023

In this connection, it is submitted that the building of SKS International Gurukul Near NIT Kirmach Road, Kurukshetra has been inspected by the concerned Junior Engineer and recommended by the Sub Divisional Engineer, Provincial Sub Division No.3, PWD B&R, Pipli and stated that the above said building found to be safe as per visual inspection. The school Building Safety Certificate is hereby given upto the period 2023-24 with the following conditions as per recommendations received from the SDE, PSD-3, Pipli:-

1. Building of this school should be repaired every year.
2. Water should not be allowed to stagnate around and on the roof of the Building.
3. If Building is found cracked from anywhere, the same should be got vacated immediately and same should be got repaired immediately.
4. Institution will be responsible for safety of building from every angle and Fire-Fighting equipment should be in functional condition.
5. If the building of the school is to be extended, the same should be first approved from Structural Engineer.
6. Adequate Fire safety may be adopted in the school campus.
7. Institute shall also ensure safety precautions from false ceiling and vitrified tiles used in dado.
8. NOC may be considered as cancelled by this office if the college violates any of the above points.

Executive Engineer,
Provincial Division No.1,
PWD B&R, Kurukshetra

DA/ Nil
Endst No.

Dated

Copy forwarded to the SDE, PSD-3, PWD B&R, Pipli letter No. 712 dated

13.10.2023.

DA/ Nil

Executive Engineer,
Provincial Division No.1,
PWD B&R, Kurukshetra